






**Playscape Inspection
& Consulting Service Inc.**

Phone: 416-691-5437
 Fax: 613-476-0010
 537 County Road 35, RR2
 Picton, Ontario K0K 2T0
www.playscapeinspection.com

Surface Impact Test Report

GENERAL SITE INFORMATION			
Location:	Proctor Park Newmarket, ON	Testing Date:	October 27, 2010
		Time:	5:00pm
	Hutcheson Sand & Gravel Ltd.	Weather:	Sunny
Inspector:	John Zandarin	Temperature:	13 degrees Celsius

SURFACING INFORMATION			
Protective Surfacing	Material:	Sand	Retaining Wall or Excavated Pit: Excavated pit
	Size/Area:	13.0m x 27.4m	
Surface Condition:	Dry	Surface Temperature:	11.7 degrees Celsius
Compaction of Surface Material:	None found	Contamination of Surface Material:	Yes, gravel
Manufacturer/Supplier of Protective Surface:	Hutcheson Sand & Gravel	Contact Information for Manufacturer/Supplier:	800-461-5521
Maximum CSA Fall Height (for given surface system): pivot point of swing	221cm	Maximum Height of Equipment (for given surface system): top of barrier at rock climbing wall	275cm

TRIAXIAL TEST DROP LOCATIONS		
Location #1	Location #2	Location #3
 <p>Pivot point of belt swing</p>	 <p>Pivot point of tot swings</p>	 <p>Top of barrier at rock wall climber</p>

Respectfully submitted

John Zandarin CCPI, CMMIII